

<b>PW-5 CHECK LIST</b>	
	5/20/2004
<b><u>Before Cable Connection</u></b>	<b><u>Before Takeoff (con't)</u></b>
Check Tail Pin & Wing Pins	Cable (check release)
Check Ballast Below Seat & Tail	Controls
Remove Wing Wheel	Canopy
Master Switch On (check voltage)	Dive / Airbrakes (closed & locked)
Flight Computer Programmed	Direction of Wind
GPS Programmed (check voltage)	Cycle Spoilers and Lock
Radio Set	Emergency Plan
Water & Food	<b><u>Landing</u></b>
Cell Phone	Wind Direction
Navigation - Sectional etc...	Altitude with Angles
Parachute On	Trim
Oxygen (as required)	Radio Position (if possible)
<b><u>Before Takeoff</u></b>	Dive / Airbrakes
Trim Set > 4 - (light), 7 - (heavy)	Airspeed
Altimeter	Look
Belts	Land

<b>BEFORE DEPARTING FOR GLIDERPORT</b>	
	04/24/04
<b><u>Required:</u></b>	<b><u>Optional:</u></b>
Glider Battery (charged 12 volts)	Flight Bag
Compaq Aero 1520	PC
GPS handheld	Tool Box
Radio (or scanner) handheld	Glider battery 12v charger
Trailer Hitch (2" ball size)	Cleaning supplies
Cell Phone with charger	Towels for clean up
Water (bottle, on ground)	Oxygen
Water (Camel pak, in air)	Documents (misc.)
Food - on ground	Chair
Food - in air	Sun Screen
Wallet (money)	Bug Spray
Sun Glasses	Batteries
Hat	Change of clothes
Sun Screen	Sheets for bunk house
Log Book	Towels for shower
BlipMap	